TECHNICAL INFORMATION

TecClay 8433TMC



Composition: waxes, oil, fillers (sulfur-free), pigments

Density: approx. 0,8 g/cm³, de-aired

Color: Light brown Odor: neutral

Shelf life: at least 24 months at temperatures from 0°C/32°F to 30°C/86°F

maximum 14 days in the oven at 55°C/131°F

40°C/104°F - 55°C/131°F Working temperature:

Warming time: ~ 3 hours, depending on type and load of the oven

Degree of hardness: medium

Shore hardness A: 55 (20°C / 68°F)

Penetration (hardness): 20°C/68°F 40°C/104°F 60°C/140°F

(according to ASTM D937-92) 130 20 47 (1/10mm)insoluble in water, partially soluble in organic solvents Solubility: Toxicology: **TecClay** does not contain substances with labelling phrases

or skin irritant ingredients.

Sales information: 1 bar = 0.56 kg/1.23 lbs; volume: approx. 0.74 l

(profile approx. 6,0 x 5,4 cm; length of bar approx. 22 cm)

20 pcs in carton; 600 pcs on pallet

The values given are typical test results which should be used as a guide only. They cannot be considered as specifications or quarantees.

Safety instruction:

- Do not heat **TecClay** over the recommended temperature (55°C/131°F). Hazards:
 - Burns to the skin from molten material
 - The material can be ignited at higher temperatures;

the following instructions should therefore be followed:

- Keep well away from ignition sources
- Prevent contact with uncovered heating wires/heating coils
- Keep well away from sparks/open flames
- Do not use any combustible materials when heating the material in the oven.
- Safety data sheets are obtainable on request.

SIP-V2/01-2025 Page 1 / 2



Instructions of use:

- **TecClay** is continuous elastic and will not harden.
- Heating up to 55°C/131°F makes the material soft and elastic.
- To reach the best results we advise to heat up **TecClay** for 3 hours at 55°C/131°F. **TecClay** should not be heated over 55°C/131°F.
- At room temperature **TecClay** models stay hard so do all edges.
- The surface of a cooled down model may be processed and flattened manually or by a clay milling machine.
- As a carrier material we advise wood or styrofoam.
- Carrier material and clay stick together without the use of glue.

 The carrier material should have a coarse surface free of dust (we advise to seal foam models with shellac before loading clay).
- **TecClay** adhesive properties make it possible to load small amounts of clay to repair damaged surfaces. Changing the model is possible without any problems.
- If you want to load larger amounts of clay upon an already cooled down surface, we advise to heat up the model surface. Only this procedure guarantees a durable and stable connection of old and new clay.
- When using a heat-gun do not exceed temperatures above 55°C/131°F.
- The clay can be lacquered with ClayPeel.
- Finishing with lacquer-foils and drawing off is possible
- Soiled surfaces can be cleaned with cleaner solvent.

SIP-V2/01-2025 Page 2 / 2